



3829 Forest Parkway, Suite 500  
Wheatfield, NY USA

Phone: (716) 629-3800  
FAX: (716) 693-9162



## Certificate of Compliance

The following models, with the TG option:

**517, 817, and WW517**

Were evaluated by:

Factory Mutual Research Corporation  
1151 Boston-Providence Turnpike  
Norwood, MA 02062

They were found to comply with the following United States Standards:

FM Standard 3600  
FM Standard 3610  
FM Standard 3810

This shows that these products are Intrinsically Safe and can be used in the following Hazardous Locations:

**Class I, Division 1, Groups A, B, C, and D**

**Class I, Zone 0, AEx ia IIC**

Temperature Code T4 in and ambient of 80°C or less

When installed per the following drawings:

[CD0634](#) **517, 817 and WW517**

This is specified on the FM Certificate of Compliance [3014461](#)

The products are marked with the FM Mark and the above ratings

I declare that the above statements are factual.

Bruce R. Temple  
Certification/Regulation Lead